

## PCWI Porosity Detector Calibration

### Application

Verification of output voltage and set voltage of detectors when a load is applied to the probe.  
To ensure accuracy and to enable voltage adjustment (if necessary).

### Features

Used for checking & calibrating PCWI Porosity Detector output voltage  
Compact, lightweight hand-held unit  
Integral probe  
Conformance Certificate  
Carry Case

### DC Crest Meter Specifications

Range: 0 to 40kV (certified up to 30kV)  
400V /4kV/40kV  
Resolution: 10V / 1V / 0.1V  
Power: 9V battery / 006P, IEC6L R1,  
NEDA 1604A  
Auto power off: About 30 min  
Earth Lead: Separate  
Dimensions: Length 420mm  
Unit Weight: 300g

